

Addendum, Additions and Corrections

Lot 96 – Very minor corrections to dial condition. There is a very faint third hairline at dial perimeter at 12:30, the edge flaking that was noted between 1 and 1:15 has been patched with some small bits of white material, there is a minuscule pinpoint nick to the outer line of the minute chapter at 53.5 minutes, and we noted some small spots of surface glaze loss to the dial left of center below the pyramids.

Lot 117 – Correction. One tooth is missing from the ratchet.

Lot 119 – Correction. Occasionally repeat function will repeat incorrectly and sluggishly; this is most evident at 12:59.

Lot 233 – Correction. Running better than described! Hour and minute hands have been zeroed and the repeat now functions properly at every hour, however at 12 the watch will occasionally repeat 11 times instead of the 12 it should be.

Lot 237 – Good news correction! While confirming the dial was original, an adjustment was made and the watch now fully functions! Runs and sets properly, repeat functions properly.

Lot 239 – Two corrections. On a positive note, this watch is a half-quarter-hour repeater, not a quarter-hour repeater as originally cataloged. HOWEVER, to add to the condition report, inconsistency with repeat function was observed with further testing.