

**Addendum, Additions, Corrections & Notes**  
**Webcast Auction with Live Close**  
**September 23, 2023**

**Lot 17: ADDENDUM ADDED ON SEPTEMBER 7, 2023:** There are several dings to leading edge of hinged tops most notably on rouge side with engraved basket.

**Lot 77: ADDENDUM ADDED ON SEPTEMBER 7, 2023:** There are small chips to the star ruby rears as well as several surface running cracks to the surfaces. They are not visible on the surfaces without use of a loupe.

**Lot 113: ADDENDUM ADDED ON SEPTEMBER 12, 2023:** Several small cracks are evident in the rubber strap, most notably near the lugs. The strap appears to be structurally sound at the moment, however one should consider ordering a new strap.

**Lot 116: ADDENDUM ADDED ON AUGUST 24, 2023:** Please note that this Piguet & Meylan watch type is typically seen with a cylinder escapement. The right-angle lever escapement and compensation balance of this example likely reflects a mid-19th century conversion, where the movement's original cylinder balance assembly and escapement was updated to this more "modern" style for better timekeeping.

**Lot 395: ADDENDUM ADDED ON AUGUST 28, 2023:** Upon additional testing, the repeat function of this watch is behaving less consistently than it did in our original testing, as the repeat now only occasionally returns correct strikes apart from the noted issue of hands approximately 7 minutes out of index. The repeat is now also observed to occasionally include or omit one or two extra or missing hour strikes and also to on occasionally have a full failure to strike regardless of its hand setting.

**Lot 213: ADDENDUM ADDED ON AUGUST 28, 2023:** Please note that when the bezel and crystal of the glass tube are removed, the movement immediately rotates within its gimbals to tip the movement's fusee-side (12 position on dial side) downward. This piece likely had some type of counter-weight originally (possibly a full movement-side cover) to keep it balanced in a horizontal plane when the bezel is removed, but if so this rear counter-weight (or cover) is no longer present and the movement is not balanced to prevent its rotation when the bezel of the brass tube is removed.

**Lot 401: ADDENDUM ADDED ON SEPTEMBER 13, 2023:** The dial of this watch has been refinished.